

Cos. C

Docket No.: MAGNET 3.0-001 CIP (PATENT)

Certificate

AUG 1 3 2007

of Correction

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

Paul I. Nippes

Patent No.: 7,034,706

Issued: April 25, 2006

For: EARLY WARNING AND PROBLEM

DETECTION IN ROTATING MACHINERY

BY MONITORING SHAFT VOLTAGE AND/OR GROUNDING CURRENT

Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Dear Sir:

Enclosed herewith is a Certificate of Correction with respect to the above-identified U.S. Patent.

The corrections indicated should be made as the application originally filed does not contain such errors. There is no requirement for payment of a fee since the errors were made by the Patent Office.

We look forward to early return of the Certificate of Correction duly certified.

Dated: August 7, 2007

Respectfully submitted,

Day d P. Krivoshik

Registration No.: 39,258 LERNER, DAVID, LITTENBERG,

KRUMHOLZ & MENTLIK, LLP 600 South Avenue West

Westfield, New Jersey 07090

(908) 654-5000

Attorney for Applicant

791813_I.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1

PATENT NO.

7,034,706

APPLICATION NO.

10/750,300

ISSUE DATE

April 25, 2006

INVENTOR(S)

Paul I. Nippes

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Whereas the column numbers 9 and 10 were skipped in printing the Letters Patent, in order for the columns to be correctly numbered:

Column number "11" should read --9--.

Column number "12" should read --10--.

Column number "13" should read --11--.

Column number "14" should read --12--.

Column number "15" should read --13--.

Column number "16" should read --14--. Column number "17" should read --15--.

Column number "18" should read --16--.

Column number "19" should read --17--.

Column number "20" should read --18--.

Column number "21" should read --19--.

Column number "22" should read --20--. Column number "23" should read --21--.

Column number "24" should read --22--.

Column number "25" should read --23--.

Column number "26" should read --24--.

Column number "27" should read --25--.

Column number "28" should read --26--.

Column number "29" should read --27--.

Column number "30" should read --28--. Column number "31" should read --29--.

Column number "32" should read --30--.

Column number "33" should read --31--.

Column number "34" should read --32--.

Column number "35" should read --33--.

Column number "36" should read --34--.

MAILING ADDRESS OF SENDER (Please do not use customer number below): David P. Krivoshik LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP 600 South Avenue West Westfield, New Jersey 07090

AUG 13 2007